



Instructions

920018-000

Adaptor

Conversion

Universal Slide




Slide Setup

Mounting Instruction's for the SOLA LED Light




Position the screw on the spiral clamp against the slide as shown, and tighten with a wrench. This position is best to keep the clamp in a Compact form.



The Clamp may also be tightened By inserting a small screwdriver through this hole

Accessory Rail Go Pro Mount In:

Before beginning you must have;
(1) Universal Accessory Slide, (2) Go Pro mounting parts contained in the original package, (3) Go Pro Bicycle Mount. Using the listed parts, assemble as shown.




Exploded Parts View



Assembled View

This is the recommended setup for the clamp used to mount the Inodive light



*The Inodive Slide offers many different Mounting solutions. The one shown is for the Inodive Light.

Or a small screwdriver can be put through the hole in the Slide to tighten the clamp.