





**“INODIVE”
Combo Mount
920038-000**


Mounting Instruction's for the SOLA LED Light


Sola D-ring kit 800-0172-A


The rectangular metal piece from the D-Ring kit is used to mount the light to the Accessory Rail 

Hook the metal piece through the cutout in the mount 

Rotate D-Ring Mount down against slide 

Slide light on to mount 

Insert the nylon cap head screw into hole and tighten to secure light. **Do not over tighten**, snug is all that's needed 



Accessory Rail System Slide Setup

Universal Slide Shown below. Slides with light mounts can be converted to Universal slides by removing the light mount and installing The Universal conversion kit.

Position the screw on the spiral clamp against the slide as shown, and tighten with a wrench. This position is best to keep the clamp in a Compact form.



Slide with light INODIVE mount



Slide light on to mount and secure with thumb screw


The mounting screw holes on the slide are offset. When installing the light mount to the slide, the slide release button will be on the opposite side away from the thumb screw hole as shown above.



**“INODIVE”
Combo Mount
920038-000**

Mounting Instruction's for the SOLA LED Light

Sola D-ring kit 800-0172-A


The rectangular metal piece from the D-Ring kit is used to mount the light to the Accessory Rail 

Hook the metal piece through the cutout in the mount 

Rotate D-Ring Mount down against slide 

Slide light on to mount 

Insert the nylon cap head screw into hole and tighten to secure light. **Do not over tighten**, snug is all that's needed 



Accessory Rail System Slide Setup

Universal Slide Shown below. Slides with light mounts can be converted to Universal slides by removing the light mount and installing The Universal conversion kit.

Position the screw on the spiral clamp against the slide as shown, and tighten with a wrench. This position is best to keep the clamp in a Compact form.




Slide with light INODIVE mount




Slide light on to mount and secure with thumb screw

The mounting screw holes on the slide are offset. When installing the light mount to the slide, the slide release button will be on the opposite side away from the thumb screw hole as shown above.



To install Combo Mount; If there is a light mount present on the Slide remove it and save the screws for use later. Mount the Combo mount over the Slide (screw holes are off set so Combo Mount will only align one way). Using the screws provided with the mount attach it to the slide as shown above, do not use excessive force snug is fine. At this point you can re-install what ever light mount was originally on the Slide using the screws removed in the beginning of the installation.



To install Combo Mount; If there is a light mount present on the Slide remove it and save the screws for use later. Mount the Combo mount over the Slide (screw holes are off set so Combo Mount will only align one way). Using the screws provided with the mount attach it to the slide as shown above, do not use excessive force snug is fine. At this point you can re-install what ever light mount was originally on the Slide using the screws removed in the beginning of the installation.